BATTISON AUTO

Inspection report

IR-93-20261102

2014 Chevrolet Silverado 1500 1LT Crew Cab 4WD

Lot #000093 · Pickup


Inspection date: 2026-11-02

Inspector: BATTISON AUTO

VIN: Available on request

✓ **Satisfactory** · 0 issues recorded

01 VEHICLE OVERVIEW



Vehicle type illustration. Recorded findings are listed below.

02 INSPECTION CHECKS

Component	Result
Engine	✓ Satisfactory
Transmission	✓ Satisfactory
Brakes	✓ Satisfactory
Suspension	✓ Satisfactory
Steering	✓ Satisfactory
Tyres	✓ Satisfactory
Bodywork	✓ Satisfactory
Interior	✓ Satisfactory
Lights	✓ Satisfactory
Electrical	✓ Satisfactory

BATTISON AUTO

Inspection recorded on 2026-11-02.

This report records the listed checks on the inspection date. It is not a roadworthiness or regulatory compliance certificate.